

Work Order ID 52008

October 15, 2009 8:51:12 AM



Page 1

Item ID: D412-791-043

Accept



Setup Start



Revision ID: B

Item Name: Mapbox Assembly

Stop



Start Date: 9/11/09 Start Qty: 1.00



Cust Item ID:

Required Date: 10/09/09 Req'd Qty: 1.00

Customer:

Reference:

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Draw
Number

Draw
Rev.

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

IIN-D412-791

B

100

0.00



DC

Memo

0.00

Document Control

Photocopy bluefile & type labels per PPP 412-791-043 CHG001

8/02/10/15

HA BG 09/10/15

110

Pick Kit

0.00



Packaging

Memo

0.00

Packaging

PC 9/10/15 (2)

120

QC4- 100% Inspect kits for completeness

0.00



QC

Memo

0.00

Quality Control

2/8/01/10/15

(x2) /

Work Order ID 52008

October 15, 2009 8:51:13 AM

Page 2

Item ID: D412-791-043

Accept

Revision ID: B

Item Name: Mapbox Assembly

Setup Start

Stop

Start Date: 9/11/09 Start Qty: 1.00

Required Date: 10/09/09 Req'd Qty: 1.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

QC:

Date:

SPC (Y/N):

Date:

Run Start

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run HoursDraw
NumberDraw
Rev.Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

0.00



Packaging

Memo

0.00

Packaging

Identify and pack for shipping as per PPP D412-791-043

Location:

PPP Rev:

Draft

140

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

9/10/10 SC (24)

09/10/19 JH
09-10-14

Picklist Print

October 15, 2009 8:51:12 AM

Page 1

Work Order ID: 52008

Parent Item: D412-791-043RevB

Parent Item Name: Mapbox Assembly

Comments:

Start Date: 9/11/09

Required Date: 10/09/09

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
S 2 D3936-041RevA 1X Mapbox Assembly		Manufactured	No			110	Each	0.0000	1.0000			
S 2 MS35207-244 4X Screw		Purchased	No			110	Each	100.0000	4.0000			

52382

PC 9/10/10

PC 9/1-10 (2)

Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

ST

100

112019

100

7/1/2019

7.0 PARTS LIST

QTY -011	QTY -041	QTY -043	QTY -045	QTY -047	QTY -049	PART NUMBER	DESCRIPTION
X						D412-791-011	SAFETY ENHANCEMENT KITS COMPLETE
1	X					D412-791-041	FLASHLIGHT KIT
1		X				D412-791-043	MAPBOX KIT
1			X			D412-791-045	EXIT ILLUMINATION KIT
1				X		D412-791-047	PITOT HEAT MONITORING KIT
1					X	D412-791-049	STANDBY ATTITUDE BATTERY MONITORING KIT
	2					D3921-1	FLASHLIGHT
	4					D3922-1	CLIP
	2					D3923-1	ANGLE
	4					D3924-1	SHIM
	8					MS20426AD3-6	RIVETS
	6					MS20470AD4-5	RIVET
	4					MS21059-L3	ANCHOR NUT
	4					MS35207-264	SCREW
		1				D3936-041	MAPBOX
		4				MS35207-244	SCREW
			16			D3937-041	PHOTOLUMINESCENT STRIPS
			90			D3950-1	RIVET (INCLUDES 10 EXTRA)
				1		18-200	CONNECTOR
				4		1N4007	DIODE
				3		80-004-2-6	POTTED INSERTS
				2		D3896-1	RELAY
				1		D3897-1	ANGLE
				1		LED-50-17-BG-E0705	ANNUNCIATOR
				1		M12883/45-01	RELAY BASE
				1		M81714/16-3	TERMINAL BLOCKS TRACK
				2		M81714/2-DC1	TERMINAL BLOCKS
				1		M81714/2-DD2	TERMINAL BLOCKS

• COPYRIGHT © 2009 BY DART AEROSPACE LTD •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: B

Date: 09. 07.22

52008